
Correction

Proc. Res. Inst. Atmos. Vol. 1. p. 82.
"Equipment for the Observation of Solar Noise
at 3750 MC." Appendix II.

H. TANAKA, T. KAKINUMA, H. JINDO and T.
TAKAYANAGI

D.C. component at the output of the detector

should be divided by 2 in both cases. Accordingly,
 σ_a must be multiplied by $\sqrt{2}$; Eq. (6) should be
read

$$\sigma_a = 4 \theta \cdot F / \pi \sqrt{2 B_i}$$

The conclusion is unchanged.